

BRAKE ACTUATOR - BHG15

Models: Prius (NHW20) & Hybrid Camry (AHV40)

Published: 20 April 2021 – Operation Code: BHG15

BACKGROUND

This Service Bulletin has been issued to advise that a Warranty Extension Program has been introduced to support replacement of the Brake Actuator assembly on Prius (NHW20) & Hybrid Camry (AHV40) for the below condition, sold in Australia. Investigations by Toyota have determined that a small number of Prius & Hybrid Camry vehicles may present to Dealer's with the Engine Warning Light illuminated relating to problems with the Brake Actuator.

DESCRIPTION OF CONDITION

Some applicable vehicles may exhibit a condition where the brake, ABS, and/or TRAC warning light(s) are ON. Diagnostic Trouble Code (DTC) C1391, C1252, C1253 or C1256 may be stored. This condition may be caused by a small internal brake fluid leak inside the brake actuator.

INVOLVED VEHICLES

A total of 26,165 Toyota vehicles produced within the VIN range and production period tabled below may possibly exhibit this condition.

MODEL	WMI	VDS	CD	VIS		PRODUCTION DATE
				FROM	TO	
Hybrid Camry	6T1	53FK4	#	0X220002	0X234428	29 Jul 2009 through 14 Oct 2011
Prius	JTD	KB20U	#	00001001	00133025	04 Jun 2003 through 27 Mar 2009
				03000147	03546220	
		KB22U		07000559	07892859	
				00001089	00133119	
				03001419	03546367	
				07000001	07894033	

Note:

- although the involved vehicles are within the above VIN ranges, not all vehicles in these ranges were sold in Australia.
- # = Check digit (alpha or numeric).

ELIGIBILITY

Vehicles listed in the VIN table above that have the brake, ABS and/or TRAC warning light(s) on (and DTC C1391, C1252, C1253 or C1256, may be eligible for this campaign.

WARRANTY SUPPORT PERIOD

The Warranty Extension Program is valid only for listed vehicles as follows:

- Up to 10 years from initial first registration or 240,000 kilometres, whichever comes first.

This Warranty Extension Program does not cover any other Toyota model or any vehicle outside of the VIN range listed.

REMEDY

Your Toyota Dealer will inspect your vehicle to confirm eligibility, the condition and will conduct any necessary repairs or part replacement related to this specific condition.

INFORMATION FOR GUESTS

Guests who experience the condition described above are advised to contact their local authorised Toyota dealership. The dealership will need to verify the condition and vehicle eligibility.

Guests are advised to have their VIN available when contacting their Toyota Dealers.

If their vehicle is eligible for this Warranty Extension Program, a Toyota Dealer will make an appointment to confirm/complete this activity on their vehicle.